

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1




FIG. 2




FIG. 3






FIG. 4

3/12  
DR92003048US1 (8728-643)




Bottom electrode contact Fig. 5

4112  
 \DR920030348US1 (8728-643)



Bottom electrode contact Fig. 6

5112  
10R92003D308US1 (8728-643)



BEST AVAILABLE COPY

Bottom electrode contact Fig. 7

60112  
YDR92003D368US1 (8728-643)





Fig. 8


7112  
✓DR920030368US1 (878643)



Bottom electrode contact Fig. 89




8/12  
YDR920030348US1 (8728643)



Bottom electrode contact

Fig. 9 10

YDR92003D348US1 (8728-643)



Bottom electrode contact Fig. 11


ID 112



### Bottom electrode contact

**Fig. 12**

11/1/12  
10R920030348US1 (8728-043)




Bottom electrode contact

Fig. 13



12 112  
 YDR92003 03408US1 (8728-643)  
 Top electrode contact

50



Bottom electrode contact Fig. 14